

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	10/20/2025	Time:	6:40 PM
Name of School Corporation:	BARTHOLOMEW CONS. SCHOOL CORP.			Corp ID:	30365
Address of School Corporation:	1260 N Marr Rd				
City:	Columbus	Zip:	47201	County Number:	3
VIN:	4UZABRFC1LCLL7246	License Number:	22993	Bus Number:	204
Make of Body:	Thomas Built Buses, Inc.	Year:	2018	Make of Chassis:	Thomas Built Buses, Inc.
Bus Type:	C			Mileage:	68115
Inspection Status:	O	Inspected By:	Zach Ruble	PE:	7715

## Violations - Rejected

## Inspection Code Description

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

## Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.