REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual		**Date:** 10/24/2025	**Time:**	11:02 AM
Name of School Corporation:	RANDOLPH CENTRAL SCHOOL CORP.			**Corp ID:**	686825
Address of School Corporation:	103 N East St				
City:	Winchester	**Zip:**	47394	**County Number:**	68
VIN:	1T88T9E24E1164487		**License Number:** 5648	**Bus Number:**	6
Make of Body:	Thomas Built Buses, Inc. **Year:** 2012		**Make of Chassis:** Freightliner	**Year:**	2014
Bus Type:	D		**Mileage:** 164725		
Inspection Status:	O	**Inspected By:**	Steve Spallinger	**PE:**	6921

Violations - Rejected

Inspection Code	Description
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
54-1-1	Stanchions, guardrails, guard panels or barriers are insecurely attached
82-1-2	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
59-2-3	Stop arm does not fully extend to a right angle to the bus
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.