

## REPORT OF SCHOOL BUS INSPECTION

|                                       |                             |                        |                |                         |                |
|---------------------------------------|-----------------------------|------------------------|----------------|-------------------------|----------------|
| <b>Type of Inspection:</b>            | Semi-Annual                 | <b>Date:</b>           | 10/31/2025     | <b>Time:</b>            | 8:52 AM        |
| <b>Name of School Corporation:</b>    | SOUTHWEST DUBOIS SCH. CORP. |                        |                | <b>Corp ID:</b>         | 192110         |
| <b>Address of School Corporation:</b> | 105 W Sunset Dr             |                        |                |                         |                |
| <b>City:</b>                          | Huntingburg                 | <b>Zip:</b>            | 47542          | <b>County Number:</b>   | 19             |
| <b>VIN:</b>                           | 4DRBUAANXDB312295           | <b>License Number:</b> | 4981           | <b>Bus Number:</b>      | 17             |
| <b>Make of Body:</b>                  | IC Corporation              | <b>Year:</b>           | 2012           | <b>Make of Chassis:</b> | IC Corporation |
| <b>Bus Type:</b>                      | C                           | <b>Mileage:</b>        | 59784          | <b>Year:</b>            | 2013           |
| <b>Inspection Status:</b>             | O                           | <b>Inspected By:</b>   | Philip Lubbers | <b>PE:</b>              | 7703           |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                        |
|------------------------|-------------------------------------------|
| 57-1-5                 | Step-well light is missing or inoperative |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u>                                                            |
|------------------------|-------------------------------------------------------------------------------|
| 63-2-1                 | Tires are cut, weathered, cracked, have lumps, or breaks that expose the cord |

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**