

REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---------------------------------------|--------------------------|------------------------|------------------|-------------------------|-----------|
| Type of Inspection: | Semi-Annual | Date: | 11/3/2025 | Time: | 10:08 AM |
| Name of School Corporation: | MUNCIE COMMUNITY SCHOOLS | Corp ID: | 181970 | | |
| Address of School Corporation: | 2501 N Oakwood | | | | |
| City: | Muncie | Zip: | 47304 | County Number: | 18 |
| VIN: | 1GBJC31U471202688 | License Number: | 73848 | Bus Number: | 3 |
| Make of Body: | Collins Bus Corporation | Year: | 2007 | Make of Chassis: | Chevrolet |
| Year: | 2007 | Mileage: | 111576 | Year: | 2007 |
| Bus Type: | | Inspected By: | Steve Spallinger | PE: | 6921 |
| Inspection Status: | R | | | | |

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 23-1-5 | Any hanger, clamp or bracket is missing, loose or broken |
| 25-1-5 | See Notes: Any defect inspector deems a violation not listed |
| 45-1-4 | Switch is not identified to clearly state its purpose and to distinguish it from the other switches. |

Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

| <u>Bus Type</u> | <u>Description</u> |
|-----------------|--------------------|
|-----------------|--------------------|