

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Semi-Annual	<b>Date:</b>	11/3/2025	<b>Time:</b>	9:22 AM
<b>Name of School Corporation:</b>	NORTH MIAMI COMMUNITY SCHOOLS			<b>Corp ID:</b>	525620
<b>Address of School Corporation:</b>	PO Box 218				
<b>City:</b>	Denver	<b>Zip:</b>	46926	<b>County Number:</b>	52
<b>VIN:</b>	1GBJG31U171151196	<b>License Number:</b>	32354	<b>Bus Number:</b>	A3
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2007	<b>Make of Chassis:</b>	Chevrolet
<b>Bus Type:</b>	A2	<b>Mileage:</b>	139617	<b>Year:</b>	2007
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Randy McPike	<b>PE:</b>	7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**