

## REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Semi-Annual	Date:	11/18/2025	Time:	10:18 AM		
Name of School Corporation:	UNION SCHOOL CORPORATION			Corp ID:	686795		
Address of School Corporation:	8707 W US 36						
City:	Modoc	Zip:	47358	County Number:	68		
VIN:	1GBJG31K591154524		License Number:	80600	Bus Number:	14	
Make of Body:	Collins Bus Corporation	Year:	2009	Make of Chassis:	Chevrolet	Year:	2009
Bus Type:	A2			Mileage:	132141		
Inspection Status:	R	Inspected By:	Steve Spallinger	PE:	6921		

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-2	The seat belt cutter is not secured using a positive fastening method.
90-1-1	The trash container is not polyethylene or equivalent material
23-1-5	Any hanger, clamp or bracket is missing, loose or broken

### Violations - Out of Service

#### Inspection Code Description

#### Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.