

REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|--------------------------------|------------------------|---------------|-----------------|------------------|-------------|-------|------|
| Type of Inspection: | Re-Inspection | Date: | 11/21/2025 | Time: | 8:16 AM | | |
| Name of School Corporation: | HARMONY SCHOOL | | | Corp ID: | 330001 | | |
| Address of School Corporation: | 909 East Second St | | | | | | |
| City: | Bloomington | Zip: | 47401 | County Number: | 53 | | |
| VIN: | 1GBHG31U731105137 | | License Number: | B144AD | Bus Number: | RED | |
| Make of Body: | Girardin Minibus, Inc. | Year: | 2002 | Make of Chassis: | Chevrolet | Year: | 2003 |
| Bus Type: | | | Mileage: | 66010 | | | |
| Inspection Status: | A | Inspected By: | Mike Adams | PE: | 7407 | | |

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code Description

Bus Type Description