

# REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	11/25/2025	Time:	11:09 AM		
Name of School Corporation:	NORTHWESTERN SCHOOL CORP.			Corp ID:	343470		
Address of School Corporation:	3075 N Washington St						
City:	Kokomo	Zip:	46901	County Number:	34		
VIN:	1HA6GUB79RN003224		License Number:	28064	Bus Number:	42	
Make of Body:	Thomas Built Buses, Inc.	Year:	2025	Make of Chassis:	Chevrolet	Year:	2024
Bus Type:	A2			Mileage:	11699		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018		

## Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-2	Step-well area is weakened
56-1-4	See Notes: Any defect inspector deems a violation not listed
3-1-7	Battery compartment door is not securely fastened.
41-1-9	See Notes: Any defect inspector deems a violation not listed
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

## Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
65-2-1	Warning lights fail to operate correctly
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
51-2-1	The service door does not open or close properly
63-2-3	Any tire is flat
31-2-1	Frame is deteriorated, cracked, broken or severely bent

## Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.