

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	Date:	12/1/2025	Time:	10:16 AM
Name of School Corporation:	ELWOOD COMMUNITY SCHOOL CORP.	Corp ID:	485280		
Address of School Corporation:	1306 N Anderson St				
City:	Elwood	Zip:	46036	County Number:	48
VIN:	1GB6G2AG3A1147426	License Number:	83583	Bus Number:	A3
Make of Body:	Collins Bus Corporation	Year:	2010	Make of Chassis:	Chevrolet
Bus Type:	A2	Mileage:	141942	Year:	2010
Inspection Status:	O	Inspected By:	Brandon Steffee	PE:	8247

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-4	Any front tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.