

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection Date: 12/5/2025 Time: 10:35 AM
Name of School Corporation: AUXILIO SERVICES (MUNCIE) Corp ID: 251807
Address of School Corporation: 11260 Cornell Park Dr Suite 700
City: Cincinnati Zip: 45242 County Number: 18
VIN: 4DRBUC8P3JB577915 License Number: B515N Bus Number: M22
Make of Body: IC Corporation Year: 2016 Make of Chassis: IC Corporation Year: 2018
Bus Type: C Mileage: 82052
Inspection Status: O Inspected By: Steve Spallinger PE: 6921

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
82-1-2	See Notes: Any defect inspector deems a violation not listed
55-1-2	There is movement at any spring loaded drag link or the rod end (using hand pressure)
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
46-1-2	Any seat back or bottom is loose

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-5	Any rear tire has less than 1/32 inch tread depth when measured in any two adjacent major grooves

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.