

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	12/11/2025	Time:	9:46 AM		
Name of School Corporation:	OAK HILL UNITED SCHOOL CORP.			Corp ID:	525625		
Address of School Corporation:	PO Box 550						
City:	Converse	Zip:	46919	County Number:	52		
VIN:	4UZABRDT8ECFF6290		License Number:	1122	Bus Number:	8	
Make of Body:	Thomas Built Buses, Inc.	Year:	2013	Make of Chassis:	Freightliner	Year:	2014
Bus Type:	C			Mileage:	118810		
Inspection Status:	O	Inspected By:	Randy McPike	PE:	7018		

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
36-1-1	The latch does not secure the hood tightly
55-1-3	Power steering is inoperative
52-1-1	There are any loose, broken, or missing mountings
68-1-1	Washers do not function properly in any manner
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
34-1-1	Any headlight is inoperative
11-1-1	The front bumper does not extend to the edge of the fenders
64-1-4	Any front turn signal does not function properly

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
31-2-1	Frame is deteriorated, cracked, broken or severely bent
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).
55-2-3	Any steering component jams or inhibits safe movement
55-2-4	Tie rod end movement is greater than 1/8 inch (rotational movement is acceptable)
53-2-5	"U" bolts are loose, broken, or missing
64-2-1	Any rear turn signal does not function properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.