REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection		**Date:** 12/9/2025	**Time:**	3:49 PM
Name of School Corporation:	GOSHEN COMMUNITY SCHOOLS			**Corp ID:**	202315
Address of School Corporation:	613 E Purl St				
City:	Goshen	**Zip:**	46526	**County Number:**	20
VIN:	1GB3G3BG5F1231374		**License Number:** 42170	**Bus Number:**	253
Make of Body:	Thomas Built Buses, Inc. **Year:** 2015		**Make of Chassis:** Chevrolet	**Year:**	2015
Bus Type:	A2		**Mileage:** 87357		
Inspection Status:	O	**Inspected By:**	Joseph Hartman	**PE:**	7257

Violations - Rejected

Inspection Code	Description
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
34-1-1	Any headlight is inoperative

Violations - Out of Service

Inspection Code	Description
11-2-2	A bumper does not meet manufactures specifications
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**