

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 12/15/2025 **Time:** 1:48 PM
Name of School Corporation: MIDDLEBURY COMMUNITY SCHOOLS **Corp ID:** 202275
Address of School Corporation: 57853 N Ridge Dr
City: Middlebury **Zip:** 46540 **County Number:** 20
VIN: 1GB3G3BG3D1146577 **License Number:** 28033 **Bus Number:** 71
Make of Body: Thomas Built Buses, Inc. **Year:** 2013 **Make of Chassis:** Chevrolet **Year:** 2013
Bus Type: A1 **Mileage:** 82667
Inspection Status: O **Inspected By:** Joseph Hartman **PE:** 7257

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
11-2-2	A bumper does not meet manufactures specifications
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.