

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	12/15/2025	Time:	2:13 PM
Name of School Corporation:	ELKHART COMMUNITY SCHOOLS	Corp ID:	202305		
Address of School Corporation:	2720 California Rd				
City:	Elkhart	Zip:	46514	County Number:	20
VIN:	4DRBWTAR9PB177758	License Number:	25575	Bus Number:	105
Make of Body:	IC Corporation	Year:	2022	Make of Chassis:	IC Corporation
Bus Type:	D	Mileage:	31793	Year:	2023
Inspection Status:	O	Inspected By:	Joseph Hartman	PE:	7257

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.