

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 12/18/2025 **Time:** 1:19 PM
Name of School Corporation: ELKHART COMMUNITY SCHOOLS **Corp ID:** 202305
Address of School Corporation: 2720 California Rd
City: Elkhart **Zip:** 46514 **County Number:** 20
VIN: 4DRBUC8N3HB454415 **License Number:** 11026 **Bus Number:** 94
Make of Body: IC Corporation **Year:** 2015 **Make of Chassis:** IC Corporation **Year:** 2017
Bus Type: C **Mileage:** 118880
Inspection Status: O **Inspected By:** Joseph Hartman **PE:** 7257

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
34-1-1	Any headlight is inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
25-2-2	Reflective glass is cracked, broken, or missing

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.