

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 1/7/2026 **Time:** 9:46 AM
Name of School Corporation: LEWIS-CASS SCHOOL CORPORATION **Corp ID:** 90815
Address of School Corporation: 6422 E SR 218
City: Walton **Zip:** 46994 **County Number:** 9
VIN: 4DRBUC8N1FB716669 **License Number:** 8941 **Bus Number:** 411
Make of Body: IC Corporation **Year:** 2014 **Make of Chassis:** IC Corporation **Year:** 2015
Bus Type: C **Mileage:** 123213
Inspection Status: R **Inspected By:** Randy McPike **PE:** 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.