

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Post-Crash Inspection	Date:	1/7/2026	Time:	12:28 PM		
Name of School Corporation:	BLOOMFIELD SCHOOL DISTRICT			Corp ID:	282920		
Address of School Corporation:	PO Box 266						
City:	Bloomfield	Zip:	47424	County Number:	28		
VIN:	4DRBUSKN4DB174810		License Number:	B332X	Bus Number:	11	
Make of Body:	IC Corporation	Year:	2012	Make of Chassis:	IC Corporation	Year:	2013
Bus Type:	C		Mileage:	91608			
Inspection Status:	O	Inspected By:	Mike Adams	PE:	7407		

Violations - Rejected

Inspection Code Description

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
18-2-4	Driveshaft Tube: any original metal crack in the shaft tube greater than one quarter (1/4) inch in length, obvious cracked weld at shaft tube end, any shaft tube with obvious twist
18-2-2	Universal Joint: any independent vertical movement between opposing yoke ends great than one eight (1/8) inch, any missing universal joint bearing cap, any missing, broken or loose universal joint bearing cap
18-2-1	Yokes: any visible crack in a yoke end, any yoke mounting hardware loose, horizontal or vertical movement of slip joint yoke great than half (1/2) inch, any loose, broken or missing end fitting fastener
18-2-3	Center/carrier bearing: any broken or loose center/carrier bearing bracket, bolts or mounting hardware, any center bearing bracket crack equaling fifty (50) percent or more of the original width, more than one half (1/2) inch vertical movement of the shaft in the center bearing carrier (rubber)

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.