

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 1/13/2026      **Time:** 9:18 AM  
**Name of School Corporation:** DECATUR COUNTY COMM. SCHOOL      **Corp ID:** 161655  
**Address of School Corporation:** 1645 W SR 46  
**City:** Greensburg      **Zip:** 47240      **County Number:** 16  
**VIN:** 4DRBUSKP8AB137059      **License Number:** 753      **Bus Number:** 43  
**Make of Body:** IC Corporation      **Year:** 2008      **Make of Chassis:** IC Corporation      **Year:** 2010  
**Bus Type:** C      **Mileage:** 148934  
**Inspection Status:** O      **Inspected By:** Chris Clark      **PE:** 6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-3	Any required padding is missing
28-1-6	See Notes: Any defect inspector deems a violation not listed
59-1-4	LED type lights have 25% to 49% pixels inoperable in any one light. (NOTE: one letter in the word "STOP" equals one light)
68-1-3	Reservoir is empty

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**