

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Re-Inspection	<b>Date:</b> 1/15/2026	<b>Time:</b> 9:18 AM
<b>Name of School Corporation:</b> DECATUR COUNTY COMM. SCHOOL		<b>Corp ID:</b> 161655
<b>Address of School Corporation:</b> 1645 W SR 46		
<b>City:</b> Greensburg	<b>Zip:</b> 47240	<b>County Number:</b> 16
<b>VIN:</b> 1BAKJCSA5KF355804	<b>License Number:</b> 31564	<b>Bus Number:</b> 5
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2018	<b>Make of Chassis:</b> Blue Bird Corporation
<b>Year:</b> 2019	<b>Mileage:</b> 97354	<b>Year:</b> 2019
<b>Bus Type:</b> B		
<b>Inspection Status:</b> O	<b>Inspected By:</b> Chris Clark	<b>PE:</b> 6665

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
35-1-1	A heater motor is not operating properly
2-1-1	Required back-up lights do not function.

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type B School Bus - A conversion or body constructed and installed upon a van or front-section vehicle chassis or stripped chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. Part of the engine is beneath and/or behind the windshield and beside the driver's seat. The entrance door is behind the front wheels.**