

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Post-Crash Inspection	<b>Date:</b>	1/30/2026	<b>Time:</b>	2:12 PM
<b>Name of School Corporation:</b>	EASTBROOK COMM. SCHOOL CORP.	<b>Corp ID:</b>	272815		
<b>Address of School Corporation:</b>	560 S 900 E				
<b>City:</b>	Marion	<b>Zip:</b>	46952	<b>County Number:</b>	27
<b>VIN:</b>	4UZABRFC1MCMK9085	<b>License Number:</b>	23990	<b>Bus Number:</b>	20-7
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2020	<b>Make of Chassis:</b>	Freightliner
<b>Bus Type:</b>	C	<b>Mileage:</b>	110520	<b>Year:</b>	2021
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Randy McPike	<b>PE:</b>	7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
67-1-2	Rims are bent or loose

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).
63-2-3	Any tire is flat

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**