REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:**	2/6/2026	**Time:** 8:49 AM
Name of School Corporation:	SCOTT COUNTY SCHOOL DISTRICT 2				**Corp ID:** 727255
Address of School Corporation:	375 E McClain				
City:	Scottsburg	**Zip:**	47170		**County Number:** 72
VIN:	4DRBVAAP09A054767		**License Number:**	23492	**Bus Number:** 19
Make of Body:	IC Corporation	**Year:** 2009	**Make of Chassis:**	IC Corporation	**Year:** 2009
Bus Type:	C		**Mileage:**	137148	
Inspection Status:	R	**Inspected By:**	Mike Martin		**PE:** 7102

Violations - Rejected

Inspection Code	Description
68-1-3	Reservoir is empty
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.