

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Post-Crash Inspection **Date:** 2/10/2026 **Time:** 9:36 AM
Name of School Corporation: AUXILIO SERVICES (MUNCIE) **Corp ID:** 251807
Address of School Corporation: 11260 Cornell Park Dr Suite 700
City: Cincinnati **Zip:** 45242 **County Number:** 18
VIN: 1HA6GUBG8LN001830 **License Number:** B716T **Bus Number:** M39
Make of Body: Chevrolet **Year:** 2020 **Make of Chassis:** GMC **Year:** 2021
Bus Type: A1 **Mileage:** 47920
Inspection Status: O **Inspected By:** Steve Spallinger **PE:** 6921

Violations - Rejected

Inspection Code Description

Violations - Out of Service

Inspection Code

Description

70-2-4 Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.