

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual Date: 2/16/2026 Time: 9:02 AM
Name of School Corporation: PAOLI COMMUNITY SCHOOL CORP. Corp ID: 596155
Address of School Corporation: 501 S Elm St
City: Paoli Zip: 47454 County Number: 59
VIN: 4UZABRDD78CZ10900 License Number: B207Q Bus Number: 11
Make of Body: Freightliner Year: 2007 Make of Chassis: Freightliner Year: 2008
Bus Type: C Mileage: 208113
Inspection Status: O Inspected By: Kelly Hammond PE: 6682

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
49-1-4	Any reflector is missing, cracked, faded, or the wrong color.
20-1-9	The “anti-vandalism” device fails to operate
59-1-2	The stop arm has faded or lost reflectivity

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
51-2-1	The service door does not open or close properly

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.