# REPORT OF SCHOOL BUS INSPECTION

| | | | | | | | |
|---|---|---|---|---|---|---|---|
| **Type of Inspection:** | Registration | | | **Date:** | 2/23/2026 | **Time:** | 12:12 PM |
| **Name of School Corporation:** | | SOUTH HARRISON COMM. SCH. CORP | | | | **Corp ID:** | 313190 |
| **Address of School Corporation:** | | 315 S Harrison Dr | | | | | |
| **City:** | Corydon | **Zip:** | 47112 | | | **County Number:** | 31 |
| **VIN:** | 4UZABRDT7ECFK1793 | | | **License Number:** | 01289 | **Bus Number:** | 7 |
| **Make of Body:** | Thomas Built Buses, Inc. | **Year:** | 2013 | **Make of Chassis:** | Thomas Built Buses, Inc. | **Year:** | 2013 |
| **Bus Type:** | A1 | | | **Mileage:** | 108283 | | |
| **Inspection Status:** | R | **Inspected By:** | Mike Martin | | | **PE:** | 7102 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|
| 46-1-5 | Upholstery or padding is ripped, torn, or improperly repaired |
| 7-1-3 | Air leak at proper connection |

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

**Bus Type Description**

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**