

## REPORT OF SCHOOL BUS INSPECTION

|   |                                     |   |
|---|-------------------------------------|---|
| <b>Type of Inspection:</b> Re-Inspection                          | <b>Date:</b> 2/26/2026              | <b>Time:</b> 9:26 AM                          |
| <b>Name of School Corporation:</b> CENTRAL NOBLE COMM SCHOOL CORP |                                     | <b>Corp ID:</b> 576055                        |
| <b>Address of School Corporation:</b> 200 E Main St               |                                     |   |
| <b>City:</b> Albion   | <b>Zip:</b> 46701                   | <b>County Number:</b> 57                      |
| <b>VIN:</b> 1BAKJCJA1SF811444                                     | <b>License Number:</b> 27412        | <b>Bus Number:</b> 9                          |
| <b>Make of Body:</b> Blue Bird Corporation                        | <b>Year:</b> 2024                   | <b>Make of Chassis:</b> Blue Bird Corporation |
| <b>Year:</b> 2025   | <b>Mileage:</b> 11700               | <b>Year:</b> 2025                             |
| <b>Bus Type:</b> C  |                                     |   |
| <b>Inspection Status:</b> R                                       | <b>Inspected By:</b> Joseph Hartman | <b>PE:</b> 7257                               |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>  |
|------------------------|---|
| 59-1-9                 | There is air leak at the stop arm air bladder that does not affect the air braking system |
| 59-1-7                 | Any optional rear stop arm device or school bus crossing arm criteria is not met          |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**