REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual		**Date:** 2/27/2026	**Time:**	9:04 AM
Name of School Corporation:	BORDEN-HENRYVILLE SCHOOL CORP			**Corp ID:**	0935
Address of School Corporation:	14312 Railroad St.				
City:	Memphis	**Zip:**	47143	**County Number:**	10
VIN:	1GB6G2AG4A1168284		**License Number:** 901	**Bus Number:**	B3
Make of Body:	Chevrolet **Year:** 2010		**Make of Chassis:** Chevrolet	**Year:**	2010
Bus Type:			**Mileage:** 139729		
Inspection Status:	R	**Inspected By:**	Mike Martin	**PE:**	7102

Violations - Rejected

Inspection Code	Description
23-1-3	Any exhaust leak can be felt with the bare hand six (6) inches from the leak in any direction (with the engine idling and the system unrestricted).

Violations - Out of Service

Inspection Code	Description

Bus Type Description