

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	Date:	3/2/2026	Time:	11:59 AM
Name of School Corporation:	MAPLE CITY CHAPEL			Corp ID:	
Address of School Corporation:	2015 Lincolnway East				
City:	Goshen	Zip:	46526	County Number:	20
VIN:	1BABNBPA33F206347	License Number:	B808L	Bus Number:	1
Make of Body:	Blue Bird Corporation	Year:	2002	Make of Chassis:	Blue Bird Corporation
Bus Type:	D	Mileage:	82679	Year:	2003
Inspection Status:	O	Inspected By:	Joseph Hartman	PE:	7257

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
15-1-1	The defroster system is not working properly.
34-1-1	Any headlight is inoperative
34-1-5	See Notes: Any defect inspector deems a violation not listed
57-1-5	Step-well light is missing or inoperative
29-1-1	The flooring is improper
26-1-4	Not securely mounted
59-1-15	See Notes: Any defect inspector deems a violation not listed
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
46-1-2	Any seat back or bottom is loose
79-1-3	If equipped the emergency warning buzzer does not sound
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
35-1-1	A heater motor is not operating properly
44-1-1	Any marker light or lens is missing, cracked, faded, wrong color, or inoperative

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
50-2-1	There is no seat belt cutter in the vehicle

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.