

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	3/13/2026	<b>Time:</b>	10:48 AM
<b>Name of School Corporation:</b>	EAST NOBLE SCHOOL CORPORATION			<b>Corp ID:</b>	576060
<b>Address of School Corporation:</b>	126 W Rush St				
<b>City:</b>	Kendallville	<b>Zip:</b>	46755	<b>County Number:</b>	57
<b>VIN:</b>	1T88T9E2XF1287924	<b>License Number:</b>	8484	<b>Bus Number:</b>	15
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2014	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	D	<b>Mileage:</b>	150828	<b>Year:</b>	2014
<b>Inspection Status:</b>	R	<b>Inspected By:</b>	Joseph Hartman	<b>PE:</b>	7257

**Violations - Rejected**

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
68-1-1	Washers do not function properly in any manner
22-1-1	A dripping oil or fluid leak
75-1-6	See Notes: Any defect inspector deems a violation not listed
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle

**Violations - Out of Service**

Inspection Code Description

Bus Type Description

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**