

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual	Date: 3/17/2026	Time: 11:27 AM	
Name of School Corporation: AVON COMMUNITY SCHOOLS	Corp ID: 323315		
Address of School Corporation: 7203 E HWY 36			
City: Avon	Zip: 46123	County Number: 32	
VIN: 4DRBWTAR5PB003895	License Number: 26095	Bus Number: 90	
Make of Body: IC Corporation	Year: 2022	Make of Chassis: IC Corporation	Year: 2023
Bus Type: D	Mileage: 31052		
Inspection Status: R	Inspected By: Tyler VanNess	PE: 7583	

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
57-1-5	Step-well light is missing or inoperative
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.