REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Re-Inspection	**Date:**	3/27/2026	**Time:**	11:01 AM
Name of School Corporation:	BLACKFORD COUNTY SCHOOLS			**Corp ID:**	50515
Address of School Corporation:	668 W CR 200S				
City:	Hartford City	**Zip:**	47348	**County Number:**	5
VIN:	4DRBUC8N5KB291726	**License Number:**	22499	**Bus Number:**	118
Make of Body:	IC Corporation **Year:** 2018	**Make of Chassis:**	IC Corporation	**Year:**	2019
Bus Type:	C	**Mileage:**	122109		
Inspection Status:	R	**Inspected By:**	Steve Spallinger	**PE:**	6921

Violations - Rejected

Inspection Code	Description
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1”x5yd, 1 blunt scissor, 6 3x3” gauze pads (sterile), 4 2”x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.