REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/1/2026	**Time:**	8:37 AM
Name of School Corporation:	PERU COMMUNITY SCHOOLS			**Corp ID:**	525635
Address of School Corporation:	35 W 3rd St				
City:	Peru	**Zip:**	46970	**County Number:**	52
VIN:	1HA6GUB72PN000288	**License Number:**	26762	**Bus Number:**	6
Make of Body:	Endera **Year:** 2023	**Make of Chassis:**	Chevrolet	**Year:**	2023
Bus Type:	A2	**Mileage:**	39629		
Inspection Status:	R	**Inspected By:**	Randy McPike	**PE:**	7018

Violations - Rejected

Inspection Code	Description
35-1-1	A heater motor is not operating properly

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**