

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Re-Inspection      **Date:** 4/2/2026      **Time:** 9:28 AM  
**Name of School Corporation:** PERU COMMUNITY SCHOOLS      **Corp ID:** 525635  
**Address of School Corporation:** 35 W 3rd St  
**City:** Peru      **Zip:** 46970      **County Number:** 52  
**VIN:** 1HA6GUB72PN000288      **License Number:** 26762      **Bus Number:** 6  
**Make of Body:** Endera      **Year:** 2023      **Make of Chassis:** Chevrolet      **Year:** 2023  
**Bus Type:** A2      **Mileage:** 39629  
**Inspection Status:** A      **Inspected By:** Randy McPike      **PE:** 7018

### Violations - Rejected

Inspection Code Description

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**