

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 4/17/2026 **Time:** 11:39 AM
Name of School Corporation: BAUGO COMMUNITY SCHOOLS **Corp ID:** 202260
Address of School Corporation: 29125 CR 22 W
City: Elkhart **Zip:** 46517 **County Number:** 20
VIN: 1GB3GSBG0J1255553 **License Number:** 68124 **Bus Number:** 26
Make of Body: Thomas Built Buses, Inc. **Year:** 2018 **Make of Chassis:** Chevrolet **Year:** 2019
Bus Type: A2 **Mileage:** 123064
Inspection Status: O **Inspected By:** Joseph Hartman **PE:** 7257

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
63-1-4	Any rear tire has less than 2/32 inch tread depth when measured in any two adjacent major grooves
63-1-7	The tires on dual wheels are touching
41-1-4	There is debris in the bus. (needs cleaned/includes dirt)
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat
10-2-2	The parking brake fails to hold the bus during the testing procedure. (Note – It is NOT a violation if the test cannot be done due to OEM design)

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.
2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.