

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Annual	<b>Date:</b> 4/17/2026	<b>Time:</b> 12:53 PM	
<b>Name of School Corporation:</b> BAUGO COMMUNITY SCHOOLS	<b>Corp ID:</b> 202260		
<b>Address of School Corporation:</b> 29125 CR 22 W			
<b>City:</b> Elkhart	<b>Zip:</b> 46517	<b>County Number:</b> 20	
<b>VIN:</b> 1GB3GSBG9K1153461	<b>License Number:</b> 85644	<b>Bus Number:</b> 37	
<b>Make of Body:</b> Thomas Built Buses, Inc.	<b>Year:</b> 2018	<b>Make of Chassis:</b> AmTran	<b>Year:</b> 2019
<b>Bus Type:</b> A2	<b>Mileage:</b> 53193		
<b>Inspection Status:</b> R	<b>Inspected By:</b> Joseph Hartman	<b>PE:</b> 7257	

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
34-1-5	See Notes: Any defect inspector deems a violation not listed

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
------------------------	--------------------

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**