REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	4/20/2026	**Time:**	10:35 AM
Name of School Corporation:	NORTH LAWRENCE COMM. SCHOOLS			**Corp ID:**	475075
Address of School Corporation:	595 Stars Blvd				
City:	Bedford	**Zip:**	47421	**County Number:**	47
VIN:	1GB3GSBG3L1259177	**License Number:**	91515	**Bus Number:**	V43
Make of Body:	Chevrolet **Year:** 2020	**Make of Chassis:**	Chevrolet	**Year:**	2020
Bus Type:		**Mileage:**	42077		
Inspection Status:	A	**Inspected By:**	Zach Ruble	**PE:**	7715

Violations - Rejected

Inspection Code	Description

Violations - Out of Service

Inspection Code	Description

Bus Type	Description