# REPORT OF SCHOOL BUS INSPECTION

| | | | | | |
|---|---|---|---|---|---|
| **Type of Inspection:** | Annual | **Date:** | 4/20/2026 | **Time:** | 10:35 AM |
| **Name of School Corporation:** | NORTH LAWRENCE COMM. SCHOOLS | | | **Corp ID:** | 475075 |
| **Address of School Corporation:** | 595 Stars Blvd | | | | |
| **City:** | Bedford | **Zip:** | 47421 | **County Number:** | 47 |
| **VIN:** | 1GB3GSBG3L1259177 | **License Number:** | 91515 | **Bus Number:** | V43 |
| **Make of Body:** | Chevrolet **Year:** 2020 | **Make of Chassis:** | Chevrolet | **Year:** | 2020 |
| **Bus Type:** | | **Mileage:** | 42077 | | |
| **Inspection Status:** | A | **Inspected By:** | Zach Ruble | **PE:** | 7715 |

**Violations - Rejected**

| Inspection Code | Description |
|---|---|

**Violations - Out of Service**

| Inspection Code | Description |
|---|---|

| Bus Type | Description |
|---|---|