

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 4/29/2026 **Time:** 11:51 AM
Name of School Corporation: OAK HILL UNITED SCHOOL CORP. **Corp ID:** 525625
Address of School Corporation: PO Box 550
City: Converse **Zip:** 46919 **County Number:** 52
VIN: 4UZABRDT9FCFW6297 **License Number:** 1124 **Bus Number:** 6
Make of Body: Thomas Built Buses, Inc. **Year:** 2013 **Make of Chassis:** Freightliner **Year:** 2015
Bus Type: C **Mileage:** 183577
Inspection Status: R **Inspected By:** Randy McPike **PE:** 7018

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|----------------------------------------------------------------------------------|
| 13-1-1 | Any clearance light is missing, cracked, faded, wrong color, or inoperative |
| 44-1-1 | Any marker light or lens is missing, cracked, faded, wrong color, or inoperative |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.