

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual **Date:** 4/29/2026 **Time:** 12:16 PM  
**Name of School Corporation:** OAK HILL UNITED SCHOOL CORP. **Corp ID:** 525625  
**Address of School Corporation:** PO Box 550  
**City:** Converse **Zip:** 46919 **County Number:** 52  
**VIN:** 1GB3GSBG5G1137121 **License Number:** 39152 **Bus Number:** 1SAV  
**Make of Body:** Thomas Built Buses, Inc. **Year:** 2016 **Make of Chassis:** Chevrolet **Year:** 2016  
**Bus Type:** A2 **Mileage:** 92681  
**Inspection Status:** O **Inspected By:** Randy McPike **PE:** 7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
13-1-1	Any clearance light is missing, cracked, faded, wrong color, or inoperative
66-1-1	Required warning devices are not present

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat

### Bus Type Description

**Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:**

- 1. Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
- 2. Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**