

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b> Post-Crash Inspection	<b>Date:</b> 5/8/2026	<b>Time:</b> 9:06 AM
<b>Name of School Corporation:</b> WAWASEE COMMUNITY SCHLS		<b>Corp ID:</b> 434345
<b>Address of School Corporation:</b> 1 Warrior Path Bldg 2		
<b>City:</b> Syracuse	<b>Zip:</b> 46567	<b>County Number:</b> 43
<b>VIN:</b> 1BAKJCSA2MF372062	<b>License Number:</b> 23873	<b>Bus Number:</b> 29
<b>Make of Body:</b> Blue Bird Corporation	<b>Year:</b> 2019	<b>Make of Chassis:</b> Blue Bird Corporation
<b>Year:</b> 2021		<b>Year:</b> 2021
<b>Bus Type:</b> C	<b>Mileage:</b> 93477	
<b>Inspection Status:</b> O	<b>Inspected By:</b> Travis Harrold	<b>PE:</b> 8022

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
64-1-4	Any front turn signal does not function properly
52-1-4	Any shock absorber is broken or missing
21-1-1	Any belt is badly chaffed, cracked, broken or missing
7-1-2	ABS warning light is illuminated
59-1-15	See Notes: Any defect inspector deems a violation not listed
67-1-2	Rims are bent or loose
34-1-1	Any headlight is inoperative
61-1-4	There is an air leak from any hose, line, tank, bag, or other component of an air suspension system
82-1-2	The mirrors do not meet the outside mirror standard as set forth in 575 IAC 1-2-49
41-1-7	Non safety related signs/decorations posted.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
41-1-9	See Notes: Any defect inspector deems a violation not listed
70-1-9	If the words "EMERGENCY EXIT" does not appear on the top or bottom of the window or directly above each emergency exit window on the inside of the bus
70-1-5	There are any decals or stickers, except those required by law, in the windshield or in the windows to the immediate right or left of the driver
70-1-8	Any required reflective tape is applied in the wrong location, missing, and wrong width or badly faded
53-1-3	Any spring hanger bushings or torque leaf bushings are worn, loose, broken or missing
3-1-7	Battery compartment door is not securely fastened.
55-1-2	There is movement at any spring loaded drag link or the rod end (using hand pressure)
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
24-1-2	The bus body has loose, damaged or improperly aligned body parts. These would include rivets, bolts, and body panels and/or rub rails
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
63-2-3	Any tire is flat
65-2-1	Warning lights fail to operate correctly
7-2-1	There is no brake certification form the certification is expired or is not signed within the six-month requirement
25-2-1	Mountings are broken or bent badly enough to inhibit proper adjustment
36-2-1	The latch mechanism is missing
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94
24-2-1	There is body damage which could cause injury to persons near the bus (e.g. jagged metal edges, etc.)((Exigent circumstance can be taken into consideration to allow the bus to return home in a post crash inspection if bus is out of its district)).

**Bus Type Description**

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**