

## REPORT OF SCHOOL BUS INSPECTION

<b>Type of Inspection:</b>	Annual	<b>Date:</b>	5/12/2026	<b>Time:</b>	11:46 AM
<b>Name of School Corporation:</b>	BAUGO COMMUNITY SCHOOLS			<b>Corp ID:</b>	202260
<b>Address of School Corporation:</b>	29125 CR 22 W				
<b>City:</b>	Elkhart	<b>Zip:</b>	46517	<b>County Number:</b>	20
<b>VIN:</b>	1T7Y74D2XM1169981	<b>License Number:</b>	24345	<b>Bus Number:</b>	19
<b>Make of Body:</b>	Thomas Built Buses, Inc.	<b>Year:</b>	2019	<b>Make of Chassis:</b>	Thomas Built Buses, Inc.
<b>Bus Type:</b>	D	<b>Mileage:</b>	78777	<b>Year:</b>	2021
<b>Inspection Status:</b>	O	<b>Inspected By:</b>	Joseph Hartman	<b>PE:</b>	7257

**Violations - Rejected**

<u>Inspection Code</u>	<u>Description</u>
26-1-2	Not fully charged
35-1-1	A heater motor is not operating properly
68-1-3	Reservoir is empty
22-1-1	A dripping oil or fluid leak
23-1-5	Any hanger, clamp or bracket is missing, loose or broken
7-1-3	Air leak at proper connection

**Violations - Out of Service**

<u>Inspection Code</u>	<u>Description</u>
59-2-3	Stop arm does not fully extend to a right angle to the bus
70-2-4	Audible warning device, when required, is not working properly. Buzzers are required after 5-2-94

**Bus Type Description**

**Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.**