

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Annual **Date:** 5/14/2026 **Time:** 8:58 AM  
**Name of School Corporation:** TAYLOR COMMUNITY SCHOOL CORP. **Corp ID:** 343460  
**Address of School Corporation:** 3750 E CR 300 S  
**City:** Kokomo **Zip:** 46902 **County Number:** 34  
**VIN:** 4UZABRFCXSCVA9333 **License Number:** 27170 **Bus Number:** 27  
**Make of Body:** Thomas Built Buses, Inc. **Year:** 2024 **Make of Chassis:** Freightliner **Year:** 2025  
**Bus Type:** C **Mileage:** 20571  
**Inspection Status:** R **Inspected By:** Randy McPike **PE:** 7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
28-1-2	The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment."
50-1-2	The seat belt cutter is not secured using a positive fastening method.
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement

### Violations - Out of Service

Inspection Code Description

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**