REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/14/2026	**Time:**	10:05 AM
Name of School Corporation:	TAYLOR COMMUNITY SCHOOL CORP.			**Corp ID:**	343460
Address of School Corporation:	3750 E CR 300 S				
City:	Kokomo	**Zip:**	46902	**County Number:**	34
VIN:	1GB3GRBG3G1189324	**License Number:**	39000	**Bus Number:**	22
Make of Body:	Starcraft **Year:** 2015	**Make of Chassis:**	Chevrolet	**Year:**	2016
Bus Type:	A2	**Mileage:**	78506		
Inspection Status:	R	**Inspected By:**	Randy McPike	**PE:**	7018

Violations - Rejected

Inspection Code	Description
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1”x5yd, 1 blunt scissor, 6 3x3” gauze pads (sterile), 4 2”x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.
68-1-3	Reservoir is empty
49-1-4	Any reflector is missing, cracked, faded, or the wrong color.

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type A School Bus - A conversion or body constructed upon a van-type or cutaway front-section vehicle with a left side driver's door, designed for carrying more than ten (10) persons. The term includes two (2) classifications:

1. **Type A-1, with a gross vehicle weight rating of ten thousand (10,000) pounds and under.**
2. **Type A-2, with a gross vehicle weight rating over ten thousand (10,000) pounds.**