

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 5/14/2026 **Time:** 11:10 AM
Name of School Corporation: TAYLOR COMMUNITY SCHOOL CORP. **Corp ID:** 343460
Address of School Corporation: 3750 E CR 300 S
City: Kokomo **Zip:** 46902 **County Number:** 34
VIN: 4UZABRFC1JCJS1460 **License Number:** 18283 **Bus Number:** 19
Make of Body: Thomas Built Buses, Inc. **Year:** 2017 **Make of Chassis:** Freightliner **Year:** 2018
Bus Type: C **Mileage:** 147439
Inspection Status: R **Inspected By:** Randy McPike **PE:** 7018

Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--|
| 28-1-4 | The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction. |

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.