

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Annual **Date:** 5/15/2026 **Time:** 9:13 AM
Name of School Corporation: TAYLOR COMMUNITY SCHOOL CORP. **Corp ID:** 343460
Address of School Corporation: 3750 E CR 300 S
City: Kokomo **Zip:** 46902 **County Number:** 34
VIN: 4UZABRFC0RCUF1937 **License Number:** 26056 **Bus Number:** 15
Make of Body: Thomas Built Buses, Inc. **Year:** 2022 **Make of Chassis:** Freightliner **Year:** 2024
Bus Type: C **Mileage:** 61143
Inspection Status: R **Inspected By:** Randy McPike **PE:** 7018

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
28-1-2	The first aid or bodily fluid (optional) kit is not securely mounted, inside, in a location accessible to the driver in plain view, or if in a bulkhead or storage compartment, is not secured, or the cover of the bulkhead/storage compartment is not clearly labeled "Emergency Equipment."
49-1-4	Any reflector is missing, cracked, faded, or the wrong color.
70-1-10	If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

Violations - Out of Service

Inspection Code Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.