

## REPORT OF SCHOOL BUS INSPECTION

**Type of Inspection:** Post-Crash Inspection      **Date:** 5/15/2026      **Time:** 11:32 AM  
**Name of School Corporation:** M.S.D. WABASH COUNTY SCHOOLS      **Corp ID:** 858050  
**Address of School Corporation:** 204 N 300 W  
**City:** Wabash      **Zip:** 46992      **County Number:** 85  
**VIN:** 4DRBUC8P7KB019860      **License Number:** 22127      **Bus Number:** 51  
**Make of Body:** IC Corporation      **Year:** 2018      **Make of Chassis:** IC Corporation      **Year:** 2019  
**Bus Type:** C      **Mileage:** 96070  
**Inspection Status:** O      **Inspected By:** Randy McPike      **PE:** 7018

### Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
11-1-2	The front or rear bumper is not properly attached, missing, torn, loose, or altered.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)

### Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-2	Door glass is missing
20-2-4	Emergency door is not securely fastened to body
14-2-1	Any crossmember is cracked or broken
31-2-1	Frame is deteriorated, cracked, broken or severely bent
62-2-1	Two (2) or more taillights or brake lights do not function (LED lights are considered non-functional if 50% or more pixels are inoperable in one light.)
64-2-1	Any rear turn signal does not function properly
24-2-2	Any body surface protrudes beyond the normal limits of the body structure

### Bus Type Description

**Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.**