

REPORT OF SCHOOL BUS INSPECTION

Type of Inspection: Spot Checks	Date: 5/20/2026	Time: 12:34 PM
Name of School Corporation: MARQUETTE HIGH SCHOOL	Corp ID: 71002Z	
Address of School Corporation: 306 W 10th St.		
City: Michigan City	Zip: 46306	County Number: 46
VIN: 4DRBUSKP0CB398768	License Number: B510V	Bus Number: 6
Make of Body: IC Corporation	Year: 2010	Make of Chassis: IC Corporation
Year: 2012		
Bus Type: C	Mileage: 93971	
Inspection Status: O	Inspected By: TOM DEVRIES	PE: 6162

Violations - Rejected

<u>Inspection Code</u>	<u>Description</u>
50-1-2	The seat belt cutter is not secured using a positive fastening method.
41-1-5	There are loose items that would create a hazard. (Broom, Scraper, Items on dash etc.)
90-1-3	The trash container is not secured to prevent movement and does not allow for easy removal and replacement
46-1-5	Upholstery or padding is ripped, torn, or improperly repaired
26-1-4	Not securely mounted
28-1-4	The first aid kit is not complete: One (1) package adhesive bandages; containing a total of sixteen (16) 1" x 3" bandages, 1 roll 1"x5yd, 1 blunt scissor, 6 3x3" gauze pads (sterile), 4 2"x5yd gauze stretch material (nonsterile), 3 oval eye pads (sterile), 2 triangular bandages, 1 instruction.

Violations - Out of Service

<u>Inspection Code</u>	<u>Description</u>
20-2-2	Door glass is missing
8-2-1	There is no brake certification, or the certification has expired or is not signed

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.