REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	5/28/2026	**Time:**	10:03 AM
Name of School Corporation:	ELWOOD COMMUNITY SCHOOL CORP.			**Corp ID:**	485280
Address of School Corporation:	1306 N Anderson St				
City:	Elwood	**Zip:**	46036	**County Number:**	48
VIN:	4DRBRABP14B962909	**License Number:**	19547	**Bus Number:**	18
Make of Body:	IC Corporation **Year:** 2003	**Make of Chassis:**	IC Corporation	**Year:**	2004
Bus Type:	C	**Mileage:**	72819		
Inspection Status:	R	**Inspected By:**	Brandon Steffee	**PE:**	8247

Violations - Rejected

Inspection Code	Description
29-1-2	Floor covering is missing, cut, loose, buckled, bulging, or not secure
49-1-2	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.