

## REPORT OF SCHOOL BUS INSPECTION

|                                |                          |                 |             |                  |                          |       |      |
|--------------------------------|--------------------------|-----------------|-------------|------------------|--------------------------|-------|------|
| Type of Inspection:            | Re-Inspection            | Date:           | 6/1/2026    | Time:            | 8:55 AM                  |       |      |
| Name of School Corporation:    | SHELBY EASTERN SCHOOLS   |                 |             | Corp ID:         | 737285                   |       |      |
| Address of School Corporation: | 2451 N 600 E             |                 |             |                  |                          |       |      |
| City:                          | Shelbyville              | Zip:            | 46176       | County Number:   | 73                       |       |      |
| VIN:                           | 1T88R4E2381103234        | License Number: | 25662       | Bus Number:      | 21                       |       |      |
| Make of Body:                  | Thomas Built Buses, Inc. | Year:           | 2008        | Make of Chassis: | Thomas Built Buses, Inc. | Year: | 2008 |
| Bus Type:                      | D                        | Mileage:        | 175100      |                  |                          |       |      |
| Inspection Status:             | O                        | Inspected By:   | Chris Clark | PE:              | 6665                     |       |      |

### Violations - Rejected

| <u>Inspection Code</u> | <u>Description</u>                                                                                           |
|------------------------|--------------------------------------------------------------------------------------------------------------|
| 65-1-6                 | LED Lights have 25% to 49% of pixels inoperable.                                                             |
| 46-1-5                 | Upholstery or padding is ripped, torn, or improperly repaired                                                |
| 69-1-3                 | Wiper blades are torn, cracked, brittle or otherwise deteriorated                                            |
| 70-1-10                | If the emergency window instructions are illegible or missing. Must be within 6 inches of the release handle |
| 23-1-5                 | Any hanger, clamp or bracket is missing, loose or broken                                                     |

### Violations - Out of Service

| <u>Inspection Code</u> | <u>Description</u> |
|------------------------|--------------------|
|------------------------|--------------------|

### Bus Type Description

Type D School Bus – A body installed upon a chassis with the engine mounted in the front, midship, or rear with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. The engine may be behind the windshield and beside the driver's seat, at the rear of the bus, behind the rear wheels, or midship between the front and rear axles. The entrance door is ahead of the front wheels.