REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/2/2026	**Time:**	10:56 AM
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)			**Corp ID:**	251807
Address of School Corporation:	11260 Cornell Park Dr Suite 700				
City:	Cincinnati	**Zip:**	45242	**County Number:**	18
VIN:	4UZABRFC7LCLJ5476	**License Number:**	B717T	**Bus Number:**	M44
Make of Body:	Freightliner **Year:** 2018	**Make of Chassis:**	Thomas Built Buses, Inc.	**Year:**	2020
Bus Type:	C	**Mileage:**	74157		
Inspection Status:	O	**Inspected By:**	Eric Parker	**PE:**	7297

Violations - Rejected

Inspection Code	Description
24-1-7	See Notes: Any defect inspector deems a violation not listed

Violations - Out of Service

Inspection Code	Description
7-2-4	Any brake line or hose is abraded (chafed), cracked, bulging or leaking (leaking at other than a proper connection).

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.