REPORT OF SCHOOL BUS INSPECTION

Type of Inspection:	Annual	**Date:**	6/2/2026	**Time:**	11:50 AM
Name of School Corporation:	AUXILIO SERVICES (MUNCIE)			**Corp ID:**	251807
Address of School Corporation:	11260 Cornell Park Dr Suite 700				
City:	Cincinnati	**Zip:**	45242	**County Number:**	18
VIN:	4DRBUC8P6JB593445	**License Number:**	B613T	**Bus Number:**	M38
Make of Body:	IC Corporation **Year:** 2016	**Make of Chassis:**	IC Corporation	**Year:**	2018
Bus Type:	C	**Mileage:**	62553		
Inspection Status:	R	**Inspected By:**	Eric Parker	**PE:**	7297

Violations - Rejected

Inspection Code	Description
67-1-5	See Notes: Any defect inspector deems a violation not listed
64-1-4	Any front turn signal does not function properly
64-1-2	A lens is cracked, missing or wrong color

Violations - Out of Service

Inspection Code	Description

Bus Type Description

Type C School Bus - A body installed upon a flat back cowl chassis with a gross vehicle weight rating of more than ten thousand (10,000) pounds and designed for carrying more than ten (10) persons. All of the engine is in front of the windshield. The entrance door is behind the front wheels.